0016

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director 801-538-5319 (TDD)

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax)

Complete: X Partial:__ Exploration: Inspection Date & Time: 6/15/94 8:00AM-11:00AM Date of Last Inspection: 5/19/94

Mine Name: Bear Canyon Mine County: E	mery Permit 1	Number:	ACT/015/02	<u>25</u>
Permittee and/or Operator's Name: Co-Op Mining	Company			
Business Address: P.O. Box 1245, Huntington, Ut				
Type of Mining Activity: Underground X Su		Plant	Other	
State Officials(s): Tom Munson	irrace rrep.	1 1ant		
Company Official(s): <u>Marlo</u>				
Federal Official(s): none				
Weather Conditions: <u>clear</u>				
Existing Acreage: Permitted-1531 Disturbed-24 1	RegradedSe	eded	Bonded- <u>24</u>	<u> </u>
Increased/Decreased: Permitted Disturbed	Regraded-	Seeded	- Bondeo	1-
Status:Exploration/Active/Inactive/Tem				
Reclamation (Phase I/Phase II/Final				
Rectalitation (Filase I/Filase II/Filiai	Bolid Release/	Liaumity	iear)	
REVIEW OF PERMIT, PERFORMANCE STANDARD	S & PERMIT CONDIT	ION REOU	IREMENTS	
	<u> </u>			
	EVALUATED	<u>N/A</u> <u>C</u>	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	\Box	[X]	
2. SIGNS AND MARKERS	[X]	Ĺ	Ц	
3. TOPSOIL	X	Ш		Ш
4. HYDROLOGIC BALANCE:	[37]	r 1	ושו	г 1
a. DIVERSIONS b. SEDIMENT PONDS AND IMPOUNDMENTS	[<u>X]</u>	上	[<u>X]</u>	<u> </u>
c. OTHER SEDIMENT CONTROL MEASURES	[X]	ፗ	[<u>X]</u>	<u> </u>
d. WATER MONITORING	[X] [X]		X	[]
e. EFFLUENT LIMITATIONS	<u>[A]</u> [Y]	<u> </u>	[<u>A]</u> [Y]	
5. EXPLOSIVES	[X] [X]	<u> </u>		H
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	ដ	급	
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENT		급	급	<u> </u>
8. NONCOAL WASTE			<u> </u>	<u> </u>
9. PROTECTION OF FISH, WILDLIFE AND	1221	ш	1t	
RELATED ENVIRONMENTAL VALUES	[X]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	<u>[X]</u>	Π	口	
11. CONTEMPORANEOUS RECLAMATION	<u>[X]</u>	口	口	\Box
12. BACKFILLING AND GRADING	[X]	$\overline{\square}$	\Box	\Box
13. REVEGETATION	[X]	\Box	\Box	
14. SUBSIDENCE CONTROL	<u>[X]</u>		$\overline{[X]}$	\Box
15. CESSATION OF OPERATIONS	[X]	\Box		\Box
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<u>[X]</u>	Щ	ĹŢ	Ц
b. DRAINAGE CONTROLS	[X]	Ц	ĻĻ	Щ
17. OTHER TRANSPORTATION FACILITIES18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	닏		
	in i	L I	[스]	<u> </u>
20. AIR QUALITY PERMIT	date) [_] [X]	<u> </u>	<u> </u>	[]
21. BONDING & INSURANCE	<u> A </u> X			· <u> </u>
	IAI	\Box	1771	



INSPECTION REPORT

(Continuation sheet)
PERMIT NUMBER: ACT/015/025

Page <u>3</u> of <u>3</u> DATE OF INSPECTION: 6/15/94

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

Spill Prevention Plan - Was updated in December of 1993 and appeared to be a detailed well delineated plan identified who to notify and the potential spill pathways.

4. HYDROLOGIC BALANCE:

<u>Diversions</u> - Diversions appeared to be in good order and were in the process of being cleaned in some areas.

<u>Sediment ponds and impoundments</u> - The sediment pond were functioning as designed and their was some water in pond B as it caught the overflow while the water truck was filling. Sediment pond inspections for ponds A,B,C were completed on 3/28/94

Water monitoring - 1ST Quarter water monitoring has been received by the Division.

<u>Effluent Limitations</u> - UPDES reports were in order for the sediment ponds and the mine water discharge.

14. SUBSIDENCE CONTROL: The data was collected in 1993 by Mr. Dan Guy.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS:

The Bath House construction is still progressing. The operator stated that the shower facility should be ready in a couple of weeks. The septic field is completed and approval from the Dept. of Health was received. Lockers are in the process of being installed. Drainage from the upper parking lot was completed as a separate ditch and discussions with Marlo recommended a possible modification to this plan to hopefully combine the drainage from the upper and lower parking areas. It was noted that a permit amendment would be required prior to implementation. This still had not been pursued at the time of this inspection, as it was merely a suggestion on the part of the inspector, and the grading was still in the process of being finalized.

21. BONDING AND INSURANCE:

A letter of credit was issued in the amount of \$340,282.00 on 1/11/94. General Liability Coverage by the Homestead Insurance Company was in effect from 1/1/94 through 1/1/95 under policy number VW80300196.

INSPECTION REPORT

(Continuation sheet)	Page	<u>3</u> of <u>3</u>
PERMIT NUMBER: ACT/015/025	DATE OF INSPECTION:	6/15/94

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Wendell Owen (Co-Op)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: / (m //mmm) #25 Date: 6/23/94